

Table of contents



1 General notes 2

2 Operating principal 3

3 Mounting instructions 3

4 Application hints 8

5 Teaching of the measuring range 10

6 Technical data 16

7 Connection diagram and pin configuration 18

8 Grounding concept 19

9 Service notes 19


10 Accessories 19

11 Troubleshooting 20

1 General notes

Appropriate use	<p>This product is a precision device which has been designed for the detection of objects and parts. It generates and provides measured values issued as electrical signals for following systems.</p> <p>Unless this product has not been specifically marked it may not be used in hazardous areas.</p>
Set-up	<p>Installation, mounting and adjustment of this product may only be executed by skilled employees.</p>
Installation	<p>Only mounting devices and accessories specifically provided for this product may be used for installation.</p> <p>Unused outputs may not be connected.</p> <p>Unused strands of hardwired sensors must be isolated. Do not exceed the maximum permissible bending radius of the cable.</p> <p>Before connecting the product electrically the system must be powered down. Where screened cables are mandatory, they have to be used in order to assure EMI protection. When assembling connectors and screened cables at customer site the screen of the cable must be linked to the connector housing via a large contact area.</p>

Laser protective measures




- The laser diode installed in the PT65 emits visible red laser lights. This laser belongs to the class 2 laser standard specified by the IEC 60825-1.
- Max. average output power < 1 mW.
- Laser radiation, do not stare into beam.
- To avoid uncontrolled laser exposure we recommend stopping the beam with a matt metal sheet.
- For laser safety reasons, the voltage supply of the sensors must be turned off when the whole system or the machine is turned off.
- Safety concept information and limiting parameters as published in the sales documentation apply at all times.

2 Operating principal

The distance measured is based on the triangulation principle. The emitted laser beam falls on the object as a small light spot and will be reflected diffusely. The position of the received light spot on the receiver (a diode line) defines the receiving angle. This angle corresponds to the distance and is the base for the internal calculations.

A distance change close to the sensor effects a large change in angle; the same distance change at the end of the measuring range has a much smaller effect to the angle. This non-linearity feature is linearized by the microcontroller. The analog output signal is linear to the distance.




The sensor adapts automatically to different object colors by varying the emitting laser intensity and optimizing the exposure time. The result is a sensor that is nearly independent on different reflections (different colors, shiny surfaces, dark objects). The sensor reaches its highest measuring accuracy if the object reflects diffusely.

3 Mounting instructions

- For a proper mounting, the mounting surface has to be flat. Be aware of the max. tightening torque.
- In case of EMC, the sensor has to be grounded and a shielded cable has to be used.
- The 90° rotating connector allows wiring the sensor from the bottom side or from the rear.
- The max. repeatability will be reached >15 minutes after power on.

Steps / Edges:


When measuring right next to steps / edges, it is important that the receiving beam is not covered by the steps / edges. This also applies to depth measurements of holes or valleys.




Mounting above shiny surfaces:

On shiny surfaces, it is important that no direct reflection can get to the receiving optics.

The reflection could blind the sensor and produce poor results. To prevent this, the sensor may be slightly tilted. The direct reflection can be seen on a white piece of paper when held in front of the receiver.




Mounting above round, shiny surfaces:




Shiny objects with a constant structure:

Especially shiny objects with a constant structure (lathed or scuffed objects, extruded aluminum profiles, etc.) could have a negative effect on the measuring result.




Objects with color edges in the same direction:

When color edges are orientated in the right direction, the effect to the measuring result will be minor. If the color edges are in the wrong direction, the effect will depend on the reflectivity of the different colors.



Profile measurement:


For profile measurements, the sensor axes should be perpendicular to the moving direction.



Several sensors without mutual optical interferences:


Several sensors, when mounted next to the other, can affect each other. When mounting a sensor, be aware that no laser spot from another sensor is within the detection range.

When mounted side by side (as shown in the picture in the middle), sensing distances up to 600mm can be achieved.


**Ambient Light**

Be careful that no strong light source faces the detection range.


3.1 Measuring Field




PT650025 / PT65002E




PT650026 / PT65002F



PT650027 / PT65002G



PT650028 / PT65002H



4 Application hints


To reach the maximum measuring accuracy of PT65 series laser distance sensors, keep an eye on the following points:

Measuring on rough surfaces

All laser distance sensors are adjusted and linearized on a reference object. The object is a white ceramic sheet with an absolutely flat surface. This is necessary for a precise adjustment in the micron range.

Many objects have a surface structure that is within the resolution of the sensor or rougher. In such a case, the sensor with its small laser spot measures the distance including the structure in contrast to a slide gauge that measures an average.

For such applications, we recommend to use a laser distance sensor with a laser line (PT66302x).



What can you do if you have color edges?

Often objects have several color edges on the surface.

For example:

Text	Pictures	Grooves	Rust	Marble

In the field, you have no guarantee that the spot is not falling on just a color edge that can cause a measuring fault. Also, when the object moves, you may get an incorrect signal for each color edge (it appears that the signal is unstable or has spikes)

In such cases, we suggest to move the object (or sensor), take several measurement values and calculate the average. The quantity of measurement values depends on the structure, the moving speed and the accuracy you desire.

Other possible solutions:




→ Use a sensor with the laser line (PT66302x).

What can you do if you have transparent, semi-transparent and highly reflective objects?

The measuring principle desires an object that reflects the light diffusely. Semi-transparent, transparent and highly reflective objects do not have this feature.

- When measuring on semi-transparent objects, the light enters the object and so the measured distance is larger than the actual distance is.
- Light will pass through a transparent object so a measuring signal is not available.
- A highly reflective object only has a direct reflection and it is not possible to work with it. For such an application, ask the Baumer electric sales staff.

→ to measure these objects, it is only possible if you place a diffuse reflecting surface on the object (sticker, etc.)

		
<p>Semi transparent objects: the light enters the object. → the measured distance is larger than the real distance</p>	<p>Transparent objects: The light passes the object without a diffuse reflection. → No measurement is possible</p>	<p>Highly reflective objects: Only direct reflection → No measurement is possible.</p>

5 Teaching of the Measuring Range


Every sensor is delivered with the factory setup (max. measuring range). The teach-in feature was designed to choose a smaller range within the nominal measuring range for optimizing the resolution and linearity. Output current, voltage and alarm output adapt to the new range. Two positions must be taught.

- The first teach-in position aligns with 0V (or 4mA), the second position aligns with 10V (or 20mA)
- These teach-in positions are always just at the border of the new range (inside the measuring range)
- The sensor may be taught more than 10,000 times in its lifetime
- The sensor can always be reset to the factory settings
- The sensor may be taught with the teach button or via the external teach input
- During the teach-in process, the red LED provides a feedback
- The red LED on the back side of the sensor indicates “run” mode if an object is within the measuring range.


Attention:

Within 5 minutes after power on, the sensor can be taught via the yellow button or the teach-in wire. After 5 minutes, the teach-in button will be locked preventing accidental adjustment. The teach-in wire is active all the time.

Example of a taught measuring range (4mA / 0V near, 20mA / 10V far)




Example of a reverse taught measuring range (4mA / 0V far, 20mA / 10V near)



PT650025 / PT65002E


Typical Resolution

Sr = taught measuring range



Typical linearity error


Sr = taught measuring range



PT650026 / PT65002F


Typical Resolution

Sr = taught measuring range




Typical linearity error

Sr = taught measuring range




PT650027 / PT65002G

Typical Resolution
Sr = taught measuring range




Typical linearity error
Sr = taught measuring range




PT650028 / PT65002H

Typische Auflösung
Sr = geteachter Messbereich



Typische Linearitätsabweichung
Sr = geteachter Messbereich




5.1 How to teach a new measuring range using the teach button

Teaching a new measuring range:

Within 5 minutes after power-up, the button can be used to teach a new range. After finishing a teach procedure, the 5 minutes start again. After the 5 minutes, the sensor does not respond to pressing the button. Seven steps to teaching a new measuring range.

1. Press (and hold) the button. The red LED will turn on, if the sensor can be taught.
2. Hold down the button for 5 more seconds. The LED will start to blink.
3. Release the button.
4. Place a target at the first new position of the measuring range. This is the position that will later produce 0V (or 4mA).
5. Briefly press the button again. The LED will stop blinking and will stay on for about 3 sec to indicate that the first position has been stored. Then the LED will blink again.
6. Now place the target at the second position (the other end of the new range), which will produce 10V (or 20mA).
7. Briefly press the button again. The LED will stop blinking and will stay on for about 3 sec to indicate that the second position has been stored. The LED will then turn off and blink once more. Now the sensor is ready to measure.


The new, smaller operating range is now set. The red LED now indicates whether an object is within the new range (LED OFF) or not (LED ON). If one of the new borders of the range was outside the standard range or the two positions were too close to each other, then the new settings are not valid. The sensor will respond with an extended blinking at the end of the teach procedure. The previous settings are still valid and the new settings are lost.



5.2 How to reset to the factory settings using the teach button

Within 5 minutes after power up, the button may be used to reset the sensor back to the factory settings. After finishing a teach procedure, the 5 minutes starts again. After the 5 minutes, the sensor does not respond to pressing the button.


1. Push the button. The red LED will turn on, if the sensor can be taught.
2. Hold down the button further 5sec. The LED will start to blink. DO NOT RELEASE the button now. Wait another 10sec until the LED is ON without blinking. Factory settings have been re-stored to the sensor.
3. Release the button.




5.3 How to teach a new range using the external teach input

Teaching the sensor via the external teach input is equivalent to the teaching procedure via the button.

Connect the external teach input line to +V_S (brown line) instead of pressing the button. There is no 5min. time limit. The sensor may be taught at any time. After finishing the teach-procedure, connect the external teach input line to 0V.




input circuit:



5.4 How to reset to the factory settings using the external teach input

To reset the sensor to factory settings via the external teach input is equivalent to the rest procedure via the button.

Connect the external teach input line to $+V_S$ (brown line) instead of pressing the button. There is no 5min. time limit. The sensor may be taught at any time. After finishing the teach-procedure, connect the external teach input line to 0V.



Time	Description of timing functions	Value	Comment
t 1	Minimum button hold time to enter teach mode	5s	Using the button, this feature can only be used within 5 minutes after power-up. Using the external teach input, it may be used at any time.
t 2	Maximum waiting time after teaching the first position	< 20s	If the button has not been pushed during this interval, the sensor will leave the teach mode without any changes.
t 3	LED on as response for the first position	ca. 3s	
t 4	Maximum waiting time after teaching the second position	< 20s	If the button has not been pushed during this interval, the sensor will leave the teach mode without any changes.
t 6	LED Blinking for "NOT OK response" after teaching the second position	ca. 5s	
t 7	Additional high time for the external teach in	0.1 ... 1s	
t 8	Pulse lengths on external teach input for first position	30 ... 2000ms	
t 9	Pulse lengths on external teach input for second position	30 ... 2000ms	
t 12	Minimum blinking time for the reset to factory settings with button	10s	
t 13	Blinking time after reset to factory settings	>0.2s	As long as the button is down or the external teach input is high
t 14	Minimum blinking time for the reset to factory settings with external teach input	10s	
t 15	Minimum high time of the external teach input after LED stops blinking for reset to factory settings	0.2s	

6 Technical Data

6.1 Devices with analog output 4 ... 20mA

	PT650025	PT650026	PT650027	PT650028
Measuring Range	30 ... 70mm	30 ... 130mm	50 ... 300mm	100 ... 600mm
Min. Teach-in range	≥ 2mm	≥ 3mm	≥ 5mm	≥ 10mm
Resolution *1)	4 ... 20µm	5 ... 60µm	0.01 ... 0.33mm	0.015 ... 0.67mm
Linearity error *2)	±12 ... ±60µm	±15 ... ±200µm	±0.03 ... ±1.0mm	±0.05 ... ±2.0mm
Response time *3)	300 ... 900µs	300 ... 900µs	300 ... 900µs	300 ... 2800µs
Interference suppression *4)	+	+	+	+
Transmitting element	Laser diode, red, pulsed			
Laser Class	2			
Wave length	650nm			
Diameter of laser spot *7)	1 ... 0.2mm	2 ... 1mm	2mm	2mm
Analog output	4 ... 20mA			
Load resistance (max.)	< (+V _S -6V) / 0,02A (900Ω @24V)			
Operating voltage	12 ... 28V DC			
Current consumption	< 100mA			
Reverse polarity protection	+			
Short circuit protection	+			
Housing material	diecast zinc			
Tightening torque (max)	1,0Nm			
Ambient light *6)	< 50kLux	< 40kLux	< 8kLux	< 10kLux
System of Protection (EN 60529)	IP 67			
Operating Temperature	0 ... +50°C (non condensing)			
Storage Temperature	-20 ... +70°C			
Temperature coefficient (typ.) *5)	±0.015%	±0.03%	±0.03%	±0.03%

*1) and *2) measured on white ceramic sheet


*3) The response time depends on the reflectivity of the object. For objects with a reflectivity < 7% the response - / release time of the PT650028 is increased automatically up to 2.8ms.

*4) Missed measurements up to 30 cycles will be suppressed. During this time the analog output stays on hold.

*5) xx % of full scale measuring range / °C

*6) Maximum sunlight on a white measuring surface

*7) dimension of laser beam:



6.1 Devices with voltage output 0 ... 10V

	PT65002E	PT65002F	PT65002G	PT65002H
Measuring Range	30 ... 70mm	30 ... 130mm	50 ... 300mm	100 ... 600mm
Min. Teach-in range	≥ 2mm	≥ 3mm	≥ 5mm	≥ 10mm
Resolution *1)	4 ... 20μm	5 ... 60μm	0.01 ... 0.33mm	0.015 ... 0.67mm
Linearity error *2)	±12 ... ±60μm	±15 ... ±200μm	±0.03 ... ±1.0mm	±0.05 ... ±2.0mm
Response time *3)	300 ... 900μs	300 ... 900μs	300 ... 900μs	300 ... 2800μs
Interference suppression *4)	+	+	+	+
Transmitting element	Laser diode, red, pulsed			
Laser Class	2			
Wave length	650nm			
Diameter of laser spot *7)	1 ... 0.2mm	2 ... 1mm	2mm	2mm
Analog output	0 ... 10V			
Load resistance (min.)	> 100kΩ			
Operating voltage	12 ... 28V DC			
Current consumption	< 100mA			
Reverse polarity protection	+			
Short circuit protection	+			
Housing material	diecast zinc			
Tightening torque (max)	1,0Nm			
Ambient light *6)	< 50kLux	< 40kLux	< 8kLux	< 10kLux
System of Protection (EN 60529)	IP 67			
Operating Temperature	0 ... +50°C (non condensing)			
Storage Temperature	-20 ... +70°C			
Temperature coefficient (typ.) *5)	±0.015%	±0.03%	±0.03%	±0.03%

*1) and *2) measured on white ceramic sheet


*3) The response time depends on the reflectivity of the object. For objects with a reflectivity < 7% the response - / release time of the PT65002H is increased automatically up to 2.8ms.

*4) Missed measurements up to 30 cycles will be suppressed. During this time the analog output stays on hold.


*5) xx % of full scale measuring range / °C

*6) Maximum sunlight on a white measuring surface

*7) dimension of laser beam:




Dimensions




7 Connection diagram and pin configuration

Connection diagram



bn=brown, wh=white, bk=black, gy=grey, bu=blue
PIN-No. of the cable socket in brackets

Pin configuration




- 1: +UB
- 2: analogue Output
- 3: 0V
- 4: n.c.
- 5: Teach-in

8 Grounding Concept

For maximum EMC protection and reliable application, use a shielded cable. Also, the sensor has to be grounded.

We recommend the grounding concept as shown in the picture. Ground the sensor with a toothed washer between the screw head and the sensor.



9 Service notes

The PT65 requires no maintenance apart from keeping the front windows clean. Dust or fingerprints can impair the sensor function. It is normally sufficient to wipe the windows dry with a clean (!), soft cloth. Alcohol or soapy water may be used for heavy soiling.

10 Accessories

Connecting cable, straight, shielded:

2m	VK205625
5m	VK505625
10m	VKA05625

Mounting bracket: **AP000031**

Protective cover (Material: Acrylic glass) **AP000041**

11 Troubleshooting

Error	Possible reason	Correction
The sensor does not Measure.	The teach-in wire is connected to +Vs.	Connect the teach-in wire to 0V.
	The receiving beam is covered by an object / edge / step.	Make sure, that no object is in the receiving field.
	No receiving signal (transparent or highly reflective object)	Make sure, that the laser spot falls on a diffuse reflecting surface.
The sensor has incorrect measuring values.	Mutual optical interferences between two or more sensors	Make sure, that no other light spot is within the receiving field of the sensor.
	Strong ambient light	Prevent ambient light with a shield
	Semi transparent, transparent or highly reflective objects	Make sure, that the laser spot falls on a diffuse reflecting surface.
The sensor does not reach the accuracy.	Rough surface	Possibly use a sensor with laser line (PT66302x).
	Color edges	Mount the sensor the correct way.
	Resolution of the A/D converter in the control unit	Read the manual of the control unit.